



Assembly Instruction | XLR Cable Connector


ORDER OF ASSEMBLY



Put chuck onto the cable.



Insert wires into the terminals and solder them.
1 = shield
2 = hot (red)
3 = cold (blue)



Prepare the cable as shown (measurements in millimeters)



Slide the bushing onto the cable.



Slide chuck to the insert.



Slide insert and chuck together into the housing.



Finish installation: Turning bushing onto the connector.

